
Meridian 1

Meridian 1

General maintenance information

Document Number: 553-3001-500

Document Release: Standard 12.00

Date: August 1996

© 1990, 1996

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules, and the radio interference regulations of Industry Canada. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses and can radiate radio frequency energy, and if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at their own expense.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

January 29, 1990

Standard, release 1.0.

February 28, 1990

Standard, release 2.0.

July 31, 1990

Standard, release 3.0.

December 1, 1991

Standard, release 4.0. This document is reissued to include technical content updates. Due to the extent of the changes, revision bars are not used.

December 31, 1992

Standard, release 5.0. This document is reissued to include information on system option 81 and equipment required for compatibility with X11 release 18. Only new information and changes to technical content are noted by revision bars in the margins.

April 1, 1993

Standard, release 6.0. Changes to technical content are noted by revision bars in the margins.

August 1, 1993

Standard, release 7.0. Changes to technical content are noted by revision bars in the margins.

April 1, 1994

Standard, release 8.0. This document is reissued to include the information on Meridian 1 option 61C. Changes to technical content are noted by revision bars in the margins.

December 1994

Standard, release 9.0. This document is reissued to include the information on Meridian 1 option 51C and other edits. Changes to technical content are noted by revision bars in the margins.

July 1995

Standard, release 10.00. This document is reissued to include information on Meridian 1 option 81C and text edits. Changes are noted by revision bars in the margins.

December 1995

Standard, release 11.00. This document is reissued to include information on the NT9D19 Call Processor Card. Changes are noted by revision bars in the margins.

August 1996

Standard, release 12.00. This document is reissued for text edits. Due to the extent of the changes, revision bars are not used.

Contents

About this document	1
References	2
Precautions	3
General precautions	3
Circuit cards	4
Data disks	6
Communicating with the system	9
System terminal	9
Message format	10
Local and remote access	11
Options 51C, 61C, 81, and 81C terminal and modem guidelines ..	12
Maintenance telephone	15
Routine maintenance	17
Pedestal air filter	17
Option 21E battery pack assembly	17
DC-power battery systems	18
Hardware maintenance tools	19
Circuit card features	19
Battery backup for CPU memory	19
Card test	19
Enable/disable switch	20
LED	20
Maintenance display code	22

CPU controls	27
Initialize button	27
Normal/maintenance switch	27
Reload button	29
System alarms	31
Major alarms	31
Minor alarms	32
Remote alarms	32
System monitor indicators	33
NT7D15 System Monitor	33
NT8D22 System Monitor	34
Line transfer	36
Main power loss	38
Module power supply failure	38
Temperature alarms	39
Software maintenance tools	41
Diagnostic programs	41
Error Monitor	42
Initialize Program	42
Midnight and Background Routines	43
Overlay Loader	45
Overload Monitor	45
Resident Trunk Diagnostic	45
System Loader	45
Options 51C, 61C, 81, and 81C features	47
The History File feature	48
Interactive diagnostics	49
The Enhanced Maintenance feature	49
Manual continuity tests	50
User reports	53
Technical assistance service	55